

## TEST REPORT

No. : XMIN2503000633CM01\_EN

Date : 2025-04-07

Page: 1 of 4



CUSTOMER NAME: POLYNEXX INDUSTRIES (YANCHENG) CO.,LTD  
 ADDRESS: NO. 3 CHUN PU ROAD, AUTO ACCESORIES INDUSTRIAL PARK,XIN  
 GOU TOWN, FUNING COUNTY, YANCHENG CITY, JIANGSU  
 PROVINCE, P.R CHINA

Sample Name : Futura Public

Above information and sample(s) was/were submitted and confirmed by the client. SGS, however, assumes no responsibility to verify the accuracy, adequacy and completeness of the sample information provided by client.

\*\*\*\*\*

Date of Receipt : 2025-03-31  
 Testing Period : 2025-03-31 ~ 2025-04-07  
 Test result(s) : For further details, please refer to the following page(s)  
 (Unless otherwise stated the results shown in this test report refer only to the sample(s) tested)

Signed for  
 SGS-CSTC Standards Technical  
 Services Co.,Ltd. Xiamen Branch.

Bryan Hong  
 Authorized signatory



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.  
 Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: [CN.Doccheck@sgs.com](mailto:CN.Doccheck@sgs.com)  
 No.31 Xianghong Road, Xiang'an Torch Industrial Zone, Xiamen, Fujian Province, China 361101 t (86-592) 5765857 www.sgsgroup.com.cn  
 中国·福建·厦门·火炬(翔安)产业区翔虹路31号 邮编: 361101 t (86-592) 5765857 sgs.china@sgs.com

## TEST REPORT

No. : XMIN2503000633CM01\_EN

Date : 2025-04-07

Page: 2 of 4

### Summary of Results:

No.	Test Item	Test Method	Result
1	Staining and Resistance to Chemicals	ISO 26987:2008	See result

### Original Sample Photo:



## TEST REPORT

No. : XMIN2503000633CM01\_EN

Date : 2025-04-07

Page: 3 of 4

Test Item: Staining and Resistance to Chemicals

Sample Description: Flooring, See photo

Test Method: ISO 26987:2008

Test Condition:

Specimen: 300mm×229mm, 1pc, cut from original sample

Precondition: at (23±2)°C, (50±5)%RH for 24h.

Procedure: The main duration of contact shall be 2h. If a stain appears on the test piece after 2h, a new test shall be conducted for a period of 30 min. After removing the contaminant, evaluate the index.

Test Result:

No.	Stain agent	Contact time	Result (Index)	Contact time	Result (Index)
1	75% alcohol disinfectant	2h	0	-	-
2	84 disinfectant	2h	0	-	-
3	Hydrogen peroxide 30% solution	2h	0	-	-
4	Quaternary ammonium salt disinfectant	2h	0	-	-
5	Miracle toilet cleaner	2h	0	-	-
6	Blue moon hand sanitizer	2h	0	-	-
7	Urine	2h	0	-	-
8	Blood	2h	0	-	-

## TEST REPORT

No. : XMIN2503000633CM01\_EN

Date : 2025-04-07

Page: 4 of 4

Note: According to ISO 26987:2008 table 1, index is interpreted and presented as follows:

Index	Effect of test after cleaning/abrasion
0	Not affected
1	Slight
2	Moderate
3	Severe

\*\*\*\*\*End of report\*\*\*\*\*